


Sensor Type: HUGEMAT



		General Dimensions			Sensing Region Dimensions							Summary			
Type	Map	Overall Length <i>L</i>	Overall Width <i>W</i>	Tab Length <i>A</i>	Matrix Width <i>MW</i>	Matrix Height <i>MH</i>	Columns		Rows	Qty.	<i>RW</i>	<i>RS</i>	Qty.	No. of Sensels	Sensel Density <small>(sensel per sq-cm)</small>
		(mm)	(mm)	(mm)	(mm)	(mm)	<i>CW</i>	<i>CS</i>			(mm)	(mm)			
HUGEMAT	5400	1060	640	120	578	884	10.0	17.0	34	10.0	17.0	52	1768	0.3	

Application Examples:
Special Features: